

Hide parts



WECON Technology Co., Ltd.

Website: <http://www.we-con.com.cn/en>

Technical Support: liux@we-con.com.cn


Skype: "fewkkj" or "Jason.chen842"

Phone: 86-591-87868869

Technical forum: <http://wecon.freeforums.net/>

Solution 1:

There is a hide function in the button parts, just like the picture below. Then you could use the bit address to control parts into hide state.



Numeric input/display [X]

General Graphic **Security** Advanced Animation

☐ Object Lock

No trigger

No trigger

☐ User Permission

☒ Hide ☐ Invisible


Control Bit HDX0.0 Edit

☒ Hide when OFF ☐ Hide when ON

确定 取消 帮助

Solution 2:

Indirect window



Double click the indirect window part.

Indirect screen No. address.For example the address=10,then Indirect window will display sub-screen 10.

Screen No.: could choose the sub-screen number,and display this screen directly.

Control display by address:use a bit address to control sub-screen display.

Indirect window

Screen

Indirect screen No. [Edit](#)

☐ Screen No.

☐ Control display by address

Position

X 599 Y 265

Size

Width 141 Height 90

[确定](#) [取消](#) [帮助](#)